



## QUARTERLY REPORT (Continued)

**ASBESTOS REMOVAL PROJECTS UNDERTAKEN DURING THE 4th QUARTER FOR CALENDAR YEAR 2005**

PROPERTY OWNER: The Boeing Company

Page 2 of 2

PROJECT DATES		JOB SITE ADDRESS OR LOCATION Specify Name of Bldg., Vessel, etc.	ASBESTOS CONTRACTOR OR EMPLOYEE NAMES	CERT #	QUANTITY REMOVED In Linear or Square Feet	
Start	Complete				Quarter	Year Total
11/19/05	11/19/05	<b>Kent Space Center</b> Facility Bldg No.: <u>18-24</u> Address or Location <u>20403 68th Ave. SE</u> City <u>Kent</u>	1. <u>Kendall Lysene</u> 2. <u>Oliver Udani</u> 3. _____ 4. _____	<u>2006019185A</u> <u>2006019741A</u> _____ _____	3 SF	13 SF

METHOD OF REMOVAL (describe): PACM gasket encapsulated and removed outside and above canopy.

COMPLIANCE PROCEDURES (describe): \_\_\_\_\_

PROJECT DATES		JOB SITE ADDRESS OR LOCATION Specify Name of Bldg., Vessel, etc.	ASBESTOS CONTRACTOR OR EMPLOYEE NAMES	CERT #	QUANTITY REMOVED In Linear or Square Feet	
Start	Complete				Quarter	Year Total
12/16/05	12/16/05	<b>Kent Space Center</b> Facility Bldg No.: <u>18-05</u> Address or Location <u>20403 68th Ave. SE</u> City <u>Kent</u>	1. <u>Kendall Lysene</u> 2. <u>Oliver Udani</u> 3. _____ 4. _____	<u>2006019185A</u> <u>2006019741A</u> _____ _____	6 LF	6 LF

METHOD OF REMOVAL (describe): Glove bag removal of ACM pipe insulation.

COMPLIANCE PROCEDURES (describe): \_\_\_\_\_

PROJECT DATES		JOB SITE ADDRESS OR LOCATION Specify Name of Bldg., Vessel, etc.	ASBESTOS CONTRACTOR OR EMPLOYEE NAMES	CERT #	QUANTITY REMOVED In Linear or Square Feet	
Start	Complete				Quarter	Year Total
		<b>Kent Space Center</b> Facility Bldg No.: _____ Address or Location <u>20403 68th Ave. SE</u> City <u>Kent</u>	1. _____ 2. _____ 3. _____ 4. _____	_____ _____ _____ _____		

METHOD OF REMOVAL (describe): \_\_\_\_\_

COMPLIANCE PROCEDURES (describe): \_\_\_\_\_

\* Attach Continuation Page for Additional Projects